



FEBRUARY 2018 MONTHLY SPECIALS




PN#RC3030-4.5
(4.5 inch Shaft)

\$37.93

BRAKE CHAMBERS

PN#RC3030SB
(Universal Length Shaft)

\$34.39




PN#RC3030CL
(Long Stroke)

\$39.95

- Manufactured by TS16949 certified factory.
- 100 % air leak test performed on all units.
- Diaphragm meets SAE standard: 1 million service times.
- **TWO YEAR NO HASSLE WARRANTY.**

SLACK ADJUSTERS



PN# RCAS1032S	Automatic 1.5 X 10 TO 5.5 HOLE. Replaces: Gunite AS1132, AS1134 Haldex 40010103, 40010143, 40910134.	\$48.16 EA
PN# RCAS1040S	Automatic 1.5 X 28 TO 5.5 HOLE. Replaces: Gunite AS1040, AS1140, AS1149 Meritor R801072, R801073, R801079 Bendix 065174, 065176	\$48.10 EA
PN# RCAS1041S	Automatic 1.5 X 28 TO 6.0 HOLE. Replaces: Gunite AS1041, AS1141, SA12023 Volvo 8084132 Mack 25QD51P3 Midland CS56041	\$52.25 EA
PN# RC400-10140	Automatic 1.5 X 28 TO 5" 6" Span. A85140. Replaces: Meritor R810300, R806024 Haldex 40910742, 40910566 Automann 1351055	\$45.61 EA
PN# RC400-10141	Automatic 1.5 X 28 TO 5.5" Span. A85141. Replaces: Meritor R806004, R806026 Haldex 40910814, 40910408 Automann 1332831 Mack 25QD410P10	\$45.61 EA
PN# RC400-10144	Automatic 1.5 X 28 TO 6" Span. Replaces: Meritor R806016, 807016 Haldex 40010144, 40910678 Automann 1332832	\$42.06 EA
PN# RC400-10155	Automatic 1.5 X 10SP X 5.5" Span Kit. Replaces: Meritor R806002 Midland 40010155 Spicer 315307 Haldex 40910085, 40910101, 40910233	\$52.61 EA

*Pictures and descriptions for reference only.

roadchampion@thetruckpeople.com

PARTS THAT KEEP YOU MOVING.

Offers expire midnight February 28th, 2018

www.thetruckpeople.com